

AN AMERICAN NATIONAL STANDARD

# Gages and Gaging for Unified Inch Screw Threads

---

ANSI/ASME B1.2-1983

(REVISION OF ANSI B1.2-1974)

*SPONSORED AND PUBLISHED BY*

THE AMERICAN SOCIETY OF MECHANICAL ENGINEERS

United Engineering Center      345 East 47th Street      New York, N. Y. 10017

# CONTENTS

Foreword .....		iii
Standards Committee Roster .....		v
<b>1 Introduction</b> .....		<b>1</b>
1.1 References .....		1
1.2 Classification .....		1
1.3 Federal Government Use .....		1
<b>2 Basic Principles</b> .....		<b>1</b>
2.1 Accuracy in Gaging .....		1
2.2 Limitations of Gaging .....		1
2.3 Determining Size of Gages .....		10
2.4 Standard Temperature .....		10
<b>3 General Practice</b> .....		<b>10</b>
3.1 General Design .....		10
3.2 Types of Gages .....		10
3.3 Interpretation of Tolerances .....		10
3.4 Direction of Tolerances on Gages .....		10
3.5 Standard Thread Gage Tolerances .....		11
3.6 Tolerance on Lead .....		11
3.7 Tolerances on Half-Angle .....		11
3.8 Check of Effect of Lead and Flank Angle Variations on Product Thread .....		11
3.9 Calibration Requirements and Standards .....		11
<b>4 Types of Gages for Product Internal Thread</b> .....		<b>11</b>
4.1 GO Working Thread Plug Gages .....		11
4.2 NOT GO (HI) Thread Plug Gages .....		13
4.3 Thread Snap Gages — GO Segments or Rolls .....		14
4.4 Thread Snap Gages — NOT GO (HI) Segments or Rolls .....		20
4.5 Thread Snap Gages — Minimum Material: Pitch Diameter Cone and Vee .....		20
4.6 Thread Snap Gages — Minimum Material: Thread Groove Diameter Type .....		23
4.7 Thread-Setting Solid Ring Gages .....		24
4.8 Plain Plug, Snap, and Indicating Gages to Check Minor Diameter of Internal Thread .....		24
4.9 Snap and Indicating Gages to Check Major Diameter of Internal Thread .....		28
4.10 Functional Indicating Thread Gages for Internal Thread .....		28
4.11 Minimum-Material Indicating Thread Gages for Internal Thread .....		33
4.12 Indicating Runout Thread Gage for Internal Thread .....		33
4.13 Differential Gaging .....		37

4.14	Pitch Micrometers .....	39
4.15	Thread-Measuring Balls .....	39
4.16	Optical Comparator and Toolmaker's Microscope .....	39
4.17	Profile Tracing Instrument .....	40
4.18	Surface Roughness Equipment .....	40
4.19	Roundness Equipment .....	40
4.20	Miscellaneous Gages and Gaging Equipment .....	40
<b>5</b>	<b>Types of Gages for Product External Thread .....</b>	<b>40</b>
5.1	GO Working Thread Ring Gages .....	40
5.2	NOT GO (LO) Thread Ring Gages .....	128
5.3	Thread Snap Gages — GO Segments or Rolls .....	129
5.4	Thread Snap Gages — NOT GO (LO) Segments or Rolls .....	131
5.5	Thread Snap Gages — Cone and Vee .....	133
5.6	Thread Snap Gages — Minimum Material: Thread Groove Diameter Type .....	133
5.7	Plain Ring and Snap Gages to Check Major Diameter of Product External Threads .....	133
5.8	Snap Gages for Minor Diameter of Product External Threads .....	135
5.9	Functional Indicating Thread Gages for External Thread .....	135
5.10	Minimum-Material Indicating Thread Gages for External Thread .....	139
5.11	Indicating Runout Gage for External Threads .....	139
5.12	Differential Gaging .....	139
5.13	W Tolerance Thread-Setting Plug Gages .....	143
5.14	Plain Check Plug Gages for Thread Ring Gages .....	148
5.15	Indicating Plain Diameter Gages — Major Diameter of Product External Threads .....	148
5.16	Indicating Gages to Check Minor Diameter of External Thread .....	148
5.17	Thread Micrometers .....	159
5.18	Thread-Measuring Wires .....	159
5.19	Optical Comparator and Toolmaker's Microscope .....	159
5.20	Profile Tracing Instrument .....	160
5.21	Electromechanical Lead Tester .....	160
5.22	Helical Path Attachment Used With GO Type Thread Indicating Gage .....	160
5.23	Helical Path Analyzer .....	160
5.24	Surface Roughness Equipment .....	161
5.25	Roundness Equipment .....	161
5.26	Miscellaneous Gages and Gaging Equipment .....	161

**Figures**

1	Maximum-Material GO Functional Limit .....	12
2	Partial End Threads and Chip Grooves .....	14
3	NOT GO (HI) Functional Diameter Limit .....	16
4	Thread Snap Gages — Maximum-Material GO Functional Limit .....	19
5	Thread Snap Gages — NOT GO (HI) Functional Diameter Limit .....	21
6	Thread Snap Gages — Minimum-Material Pitch Diameter Limit — Cone and Vee .....	22
7	Thread Snap Gages — Minimum-Material Thread Groove Diameter Limit .....	23
8	Thread Form of Solid Thread-Setting Ring Gages .....	26
9	Minor Diameter Limit — Cylindrical Plug Gages .....	27
10	Indicating Plain Diameter Gages — Max.-Min. Minor Diameter Limit and Size .....	29
11	Snap and Indicating Diameter Gages — Max.-Min. Major Diameter Limit and Size .....	30

12	Indicating Thread Gages — Maximum-Material GO Functional Limit and Size .....	31
13	Indicating Thread Gages — Minimum-Material Pitch Diameter Limit and Size — Cone and Vee .....	34
14	Indicating Thread Gages — Minimum-Material Pitch Diameter Limit and Size — Ball and Radius .....	35
15	Indicating Thread Gages — Diameter Runout — Minor to Pitch .....	36
16	Indicating Thread Gages — Differential Gaging .....	38
17	Inside Micrometer, Caliper Type .....	39
18	Maximum-Material GO Functional Limit .....	127
19	NOT GO (LO) Functional Diameter Limit .....	129
20	Thread Snap Gages — Maximum-Material GO Functional Limit .....	130
21	Thread Snap Gages — NOT GO (LO) Functional Diameter Limit .....	132
22	Thread Snap Gages — Minimum-Material Pitch Diameter Limit — Cone and Vee .....	134
23	Thread Snap Gages — Minimum-Material Thread Groove Diameter Limit .....	135
24	Major Diameter Limit .....	136
25	Minor Diameter Limit Snap Type .....	137
26	Indicating Thread Gages — Maximum-Material GO Functional Diameter Limit and Size .....	138
27	Indicating Thread Gages — Minimum-Material Pitch Diameter Limit and Size — Cone and Vee .....	140
28	Indicating Thread Gages — Minimum-Material Thread Groove Diameter Limit and Size .....	141
29	Indicating Thread Gages — Diameter Runout — Major to Pitch .....	142
30	Indicating Thread Gages — Differential Gaging .....	144
31	Thread Form of Truncated Thread-Setting Plug Gages .....	146
32	Thread Form of Full-Form Thread-Setting Plug Gages .....	147
33	Indicating Plain Diameter Gage — Max.-Min. Major Diameter Limit and Size .....	149
34	Indicating Diameter Gages — Max.-Min. Minor Diameter Limit and Size .....	150
35	Indicating Gages — Helical Path Attachment Used With GO Type Indicating Gage .....	160

## Tables

1	Screw Thread Gages and Measuring Equipment for External Product Thread Characteristics .....	2
2	Screw Thread Gages and Measuring Equipment for Internal Product Thread Characteristics .....	6
3	Recommended Widths for Chip Grooves .....	13
4	Specifications and Format for Tables 10 and 11 — Limits of Size of Threaded and Plain Gages for Unified External and Internal Threads .....	15
5	Specifications and Format for Tables 10 and 11 — Limits of Size of Thread- Setting Gages for Unified Thread Working Gages .....	17
6	X Gage Tolerances for Thread Gages .....	18
7	W Gage Tolerances for Thread Gages .....	25
8	Gage Tolerances for Plain Cylindrical Gages .....	28
9	Constants for Computing Thread Gage Dimensions .....	32
10	Gages for Standard Thread Series, Classes 1A, 2A, 3A, 1B, 2B, and 3B Unified Screw Threads — Limits of Size .....	41
11	Setting Gages for Standard Thread Series, Classes 1A, 2A, 3A, 1B, 2B, and 3B Unified Screw Threads — Limits of Size .....	83
12	Calibration Requirements and Standards for X Tolerance Thread Gages, Indicating Gages, Plain Gages, and Measuring Equipment for External Product Threads .....	151

13	Calibration Requirements and Standards for X Tolerance Thread Gages, Indicating Gages, Plain Gages, and Measuring Equipment for Internal Product Threads .....	155
14	Calibration Requirements for Thread- and Plain-Setting Gages .....	159

**Appendices**

<b>A</b>	<b>Calibration and Inspection of Limit Gages, Snap Gages, Indicating Gages, and Measuring Instruments</b>	
A1	General .....	163
A2	Thread Plug Gage Calibration .....	163
A3	Thread Ring Gage Inspection .....	164
A4	Plain Plug Gage Calibration .....	167
A5	Plain Ring Gage Calibration .....	168
A6	Plain Snap Gages .....	168
A7	Rolls With Zero Lead Thread Form Used on Snap and Indicating Gages .....	168
A8	Inspecting Peripheral Contacting Segments Used on External Product Thread .....	168
A9	Inspection of Thread Contact Segments Used on Internal Product Thread .....	170
A10	Check for Magnification Discrepancies Due to Indicating System Linkage .....	170
A11	Calibration of Dial and Electronic Indicators .....	170
A12	Assessment of Surface Quality .....	171
<b>B</b>	<b>Metrology of 60 deg. Screw Threads</b> .....	173
B1	Wire Method of Measurement of Pitch Diameter (Thread Groove Diameter) .....	173
B2	Size of Wires .....	173
B3	Methods of Measuring Wires Considering the Effect of Deformation .....	173
B4	Methods of Measurement Using Wires .....	176
B5	Standard Specification for Wires and Standard Practice in Measurement of Wires of 60 deg. Threads .....	176
B6	General Formula for Measurement of Pitch Diameter .....	177
B7	Simplified Formula for Pitch Diameter .....	177
B8	Setting Measuring Instruments With Variable Measuring Force .....	178
B9	Thread Balls .....	178
B10	Internal Pitch Diameter Measurement .....	179

**Figure**

B1	A Three-Wire Method of Measuring Pitch (Thread Groove) Diameter of Thread Plug Gages .....	174
----	--	-----

**Tables**

A1	Minimum Magnification .....	164
A2	60 deg. Included Thread Angle .....	165
A3	Lengths of AGD Taperlock and Trilock Thread Plug Gage Blanks Selected From ANSI B47.1 .....	166
A4	Lengths of AGD Thread Ring Gage Blanks and Total Thread Lengths of Standard Truncated-Setting Plug Gage Blanks Selected from ANSI B47.1 .....	169
B1	Thread-Measuring Wires for 60 deg. Screw Threads .....	175
B2	Measuring Force for Over-Wire Measurements of External Pitch Diameter and Wire Calibration, and Cylindrical Diameter for Wire Calibration .....	176
B3	Measuring Force Over Balls for Internal Pitch Diameter Measurement and Ball Calibration .....	179